

Corrections to Consolidated Test Data For Hickok Model 533A-600A-605A Tube Testers

Page	Tube	Correction	Added	Version
3	10D2	Press should be "P1" for Diode #1.	11/9/2017	2.5.1
3	10D2	Diode #2 English should be "78".	11/14/2017	2.5.1
6	12A7	Press should be "P3" for rectifier section	1/8/2020	2.5.4
6	12AF3	Fil should be "Off" for Short test only.	11/9/2017	2.5.1
8	12BY3	Fil should be "Off" for Short test only.	11/9/2017	2.5.1
8	12CS6	Grid #2 should be Grid #3.	11/10/2017	2.5.1
18	19DX3	Fil should be "Off" for Short test only.	11/9/2017	2.5.1
27	30AE3	Fil should be "25" for English reading.	11/9/2017	2.5.1
27	30R-K47	Fil should be "25" for English reading.	11/9/2017	2.5.1
28	35W4	Fil should be "BLST" for Short test.	11/9/2017	2.5.1
28	35Y4	Fil should be "BLST" for Short test.	11/9/2017	2.5.1
28	35Z5	Fil should be "BLST" for Short test.	11/9/2017	2.5.1
29	3AV6	Triode section. Delete "Make emissions test only. Good tubes..."	11/13/2017	2.5.1
30	3E5	Press should be blank.	11/10/2017	2.5.1
30	3CS6	Grid #2 should be Grid #3	11/10/2017	2.5.1
30	3DT6	Second Grid #1 should be Grid #3.	11/9/2017	2.5.1
31	40Z5	Fil should be "BLST" for Short test.	11/9/2017	2.5.1
32	4CS6	Grid #2 should be Grid #3	11/10/2017	2.5.1
32	4DT6	Grid #2 should be Grid #3.	11/9/2017	2.5.1
33	4GW5	Fil should be "4.3" instead of "5".	11/9/2017	2.5.1
34	50Y7	Fil should be "50" for English readings.	11/9/2017	2.5.1
34	50Z7	Fil should be "BLST" for Short test.	11/9/2017	2.5.1
36	5742	Fil should be "4.3" instead of "6.3".	11/9/2017	2.5.1
47	6AF3	Fil should be "Off" for Short test only.	11/9/2017	2.5.1
48	6AL3	Fil should be "6.3" for English reading.	11/9/2017	2.5.1
51	6BJ8	Diode #2 English should be "78".	11/14/2017	2.5.1
54	6CS6	Grid #2 should be Grid #3	11/10/2017	2.5.1
55	6DK3	Fil should be "Off" for Short test only.	11/9/2017	2.5.1
55	6DL3	Fil should be "6.3" for English reading.	11/9/2017	2.5.1
55	6DT6	Grid #2 should be Grid #3.	11/9/2017	2.5.1
59	6GY8	Fil should be "Off" for second Short test only.	11/9/2017	2.5.1
59	6GY8	Fil should be "6.3" for Triodes #1, #2, & #3.	11/9/2017	2.5.1

Corrections to Consolidated Test Data For Hickok Model 533A-600A-605A Tube Testers

Page	Tube	Correction	Added	Version
63	6LF8	Bias should be "6".	10/15/2018	2.5.3
64	6ME8	Selector setting should be EV-6837-1 for Plate #2.	1/8/2020	2.5.4
65	6N8	Press should be "P4" for Pentode section. Press should be "P1" for Diode #2.	11/10/2017	2.5.1
66	6SK7	Eng should be "73"	3/7/2018	2.5.2
67	6V3	Fil should be "Off" for Short test only.	11/9/2017	2.5.1
73	84	Plate #1 Selectors setting incorrect. Should be JR-0304-0.	11/9/2017	2.5.1
78	9AK8	Press should be "P4" for Triode section. Press should be "P1" for Diode #3.	11/10/2017	2.5.1
81	DAF92	Pentode section delete "Hold down P1 and Press P4."	11/14/2017	2.5.1
81	DH77	Press should be "P1" for Diode #2.	11/9/2017	2.5.1
81	DL67	Delete "Hold down P1 and Press P4."	11/14/2017	2.5.1
84	EBF89	Press for Pentode section should be "P4".	11/9/2017	2.5.1
86	ECH83	After Heptode & Pentode section add "Reading is made on English scale only. Make no gas test.	11/13/2017	2.5.1
88	EY88	Fil should be "6.3" for English reading.	11/9/2017	2.5.1
90	HY90	Fil should be "BLST" for Short test.	11/9/2017	2.5.1
91	LY88	Fil should be "20" for English reading.	11/9/2017	2.5.1
94	PY88	Fil should be "25" for English reading.	11/9/2017	2.5.1
96	UBC41	UBC42 & UBC43 are part of UBC41 and should be combined.	11/10/2017	2.5.1
98	XY88	Fil should be "Off" for Short test. Press should be "P3" for English test.	11/10/2017	2.5.1
98	ZD152	Press should be "P1" for Diode #1 and #2.	11/10/2017	2.5.1
98	ZD17	Press should be "P1" for Diode section.	11/10/2017	2.5.1